

حدود عناصر پایه نیکل

Element	Low	High
Al	0.001	15.0
B	0.0005	1.90
C	0.001	0.50
Co	0.001	22.0
Cr	0.001	53.0
Cu	0.001	35.0
Fe	0.0005	50.0
Hf	0.005	2.20
Mg	0.0005	0.17
Mn	0.001	3.20
Mo	0.001	36.0
Nb	0.001	8.0
P	0.0003	0.06
Pb	0.001	0.07
S	0.0005	0.13
Si	0.0001	7.0
Sn	0.0005	0.70
Ta	0.005	7.0
Ti	0.005	6.30
V	0.001	1.20
W	0.005	13.50
Zr	0.001	0.28